

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERTL. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection:						
OGM	Steve Demczak Environmental Scientist III					
Company	Boyd Rhodes					

Inspection Report

Permit Number:	C0070022		
Inspection Type:	PARTIAL		
Inspection Date:	Monday, June 14, 2004		
Start Date/Time:	6/14/2004 11:00:00 AM		
End Date/Time:	6/14/2004 2:00:00 PM		
Last Inspection:	Wednesday, May 26, 2004		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Sunny, Warm 70's InspectionID Report Number: 305

Accepted by: pgrubaug

7/28/2004

Permitee: SAVAGE SERVICES Operator: SAVAGE SERVICES

Site: SAVAGE COAL TERMINAL

Address: 6340 \$ 3000 E STE 600, SALT LAKE CITY UT 84121

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operation		
160.00	Total Permitted	Federal	✓ Underground		
122.28	Total Disturbed	☐ State	Surface		
	Phase I	County	✓ Loadout		
	Phase II	Fee	Processing		
	Phase III	✓ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Permit Conditions- The permittee must submit water quality data, by using the electronic water quality data system.

The permittee has submitted permit renewal information to the Division. The task number is 1902.

No violations have been issued.

Inspector's Signature

Steve Demczak, Environmental Scientist III

Date

Thursday, June 17, 2004

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Monday, June 14, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		~	
2.	Signs and Markers	✓		\checkmark	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	V		✓	
8.	Noncoal Waste	✓		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.	a Roads: Construction, Maintenance, Surfacing				
16.	b Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check	✓		V	
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070022 Inspection Type: PARTIAL

Inspection Date: Monday, June 14, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee has not submitted any new amendments to the Division since the last inspection. The permittee submitted information for the permit renewal. This is task #1902 and is due to be completed on July 28, 2004.

2. Signs and Markers

The identification signs at the gates to the property were inspected and complied with the R645 Coal Rules.

3. Topsoil

Tthe permittee installed a four to five foot silt fence along the haul road to prevent coal fines from going on to the topsoil pile.

4.a Hydrologic Balance: Diversions

The diversion ditches were spot-checked and were functioning as designed. The permittee has cleaned out several diversions since the last inspection.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Several of the sediment ponds did contain water but were not discharging. No hazardous conditions were noticed during the inspection. The permittee plans in cleaning out several of the sediment ponds during the summer.

7. Coal Mine Waste, Refuse Piles, Impoundments

The permittee has re-graded the outslopes of refuse pile. Rills had occurred during the snow melt this past spring. No hazardous conditions were noticed during the inspection.

8. Noncoal Waste

The area was generally clear of non-coal waste material.

19. AVS Check

An AVS check was made and no information was available in the system to compare with the Mining and Reclamation Plan.